

Quick-Change Tooling Systems

Jacobs Taper Quick-Change Adapters

#30 Taper

Jacobs Taper	Code
J1	302160
J2	302161
J3	302162
J33	302163
J4	302164
J6	302165



#40 Taper

Jacobs Taper	Code
J1	302170
J2	302171
J3	302172
J33	302173
J4	302174
J6	302175

Collet Chuck Quick-Change Adapters

#30 Taper

Capacity (Inch)	Code
1/8 - 1	302195



#40 Taper

Capacity (Inch)	Code
1/8 - 1	302196

Morse Taper Quick-Change Adapters

#30 Taper

Morse Taper	Code
MT1	302136
MT2	302137
MT3	302138
MT4	302139

NOTE: ISA30 ad ISA40 Quick-Change Adapters can be used on regular machine spindles. Standard ISA30 and ISA40 adapters cannot be used on these master shanks



#40 Taper

Morse Taper	Code
MT2	302147
MT3	302148
MT4	302149

NOTE: ISA30 ad ISA40 Quick-Change Adapters can be used on regular machine spindles. Standard ISA30 and ISA40 adapters cannot be used on these master shanks