


Dead Centers



Carbide Tipped



- ± 0.0001 " total indicator runout

Morse Taper	L (Inch)	D (Inch)	E (Inch)	Weight (lbs)	Code
1	3.15	0.48	0.28	0.13	826311
2	3.94	0.71	0.28	0.44	826312
3	4.92	0.95	0.43	0.66	826313
4	6.30	1.24	0.55	1.50	826314
5	7.87	1.76	0.71	4.00	826315
6	10.63	2.51	0.71	11.50	826316

Dead Centers



Half Dead Centers

Carbide Tipped



- ± 0.0001 " total indicator runout

Morse Taper	L (Inch)	D (Inch)	E (Inch)	Weight (lbs)	Code
1	3.15	0.48	0.28	0.13	826317
2	3.94	0.71	0.28	0.44	826318
3	4.92	0.95	0.43	0.66	826319
4	6.30	1.24	0.55	1.50	826320
5	7.87	1.76	0.71	4.00	826321
6	10.63	2.51	0.71	11.50	826322