


Dead Centers




- Ball bearing steel
- ± 0.0001 " total indicator runout

Morse Taper	L (Inch)	D (Inch)	E (Inch)	Weight (lbs)	Code
1	3.15	0.48	0.28	0.13	826299
2	3.94	0.71	0.28	0.44	826300
3	4.92	0.95	0.43	0.66	826301
4	6.30	1.24	0.55	1.50	826302
5	7.87	1.76	0.71	4.00	826303
6	10.63	2.51	0.71	11.50	826304

Dead Centers



Half Dead Centers



- ± 0.0001 " total indicator runout

Morse Taper	L (Inch)	D (Inch)	E (Inch)	Weight (lbs)	Code
1	3.15	0.48	0.28	0.13	826305
2	3.94	0.71	0.28	0.44	826306
3	4.92	0.95	0.43	0.66	826307
4	6.30	1.24	0.55	1.50	826308
5	7.87	1.76	0.71	4.00	826309
6	10.63	2.51	0.71	11.50	826310