

Dead Centers

High Speed Steel/Carbide Tipped




High Speed Steel

Morse Taper	Code	Morse Taper	Code	Morse Taper	Code
1	125101	3	125103	5	125105
2	125102	4	125104	6	125106

Carbide Tipped

Morse Taper	Code	Morse Taper	Code	Morse Taper	Code
1	125111	3	125113	5	125115
2	125112	4	125114	6	125116

Automatic Face Drivers



- Save set-up time! One setting for machining various workpieces
- Heavier cuts without slippage
- Higher concentricity and accuracy
- Most effective driving action even with irregular faces
- All components of the drive plates are hardened for long life

NOTE: Drivers supplied right hand

Morse Taper	D (Inch)	D1 Drive Plate Diameter (Inch)	A (Inch)	B (Inch)	L (Inch)	Weight (lbs)	Code
4	2.68	1.063	2.52	3.15	7.28	4.41	826293
4	3.19	1.575	2.64	3.23	7.36	5.95	826294
5	2.68	1.063	2.48	3.11	8.35	6.61	826295
5	3.19	1.575	2.48	3.11	8.35	7.50	826296
5	3.54	1.969	3.39	4.67	9.94	11.46	826297
5	3.94	2.480	3.39	4.67	9.94	14.33	826298