



Throw Away Cutters

Cobalt M42 – 3 Flute – Center Cut – Weldon Shanks



Stub Length



Long Length



Cutter Diameter (Inch)	Shank Diameter (Inch)	Length of Cut (Inch)	Overall Length (Inch)	Code
1/16	1/4	3/32	31/32	313164
3/32	1/4	5/32	1-1/64	313165
1/8	1/4	3/16	1-3/32	313166
5/32	1/4	1/4	1-9/32	313167
3/16	1/4	9/32	1-11/32	313168
7/32	1/4	5/16	1-13/32	313169
1/4	1/4	3/8	1-13/32	313170

Cutter Diameter (Inch)	Shank Diameter (Inch)	Length of Cut (Inch)	Overall Length (Inch)	Code
1/16	1/4	5/32	1-3/32	313171
3/32	1/4	1/4	1-1/4	313172
1/8	1/4	5/16	1-11/32	313173
5/32	1/4	3/8	1-17/32	313174
3/16	1/4	7/16	1-21/32	313175
7/32	1/4	1/2	1-3/4	313176
1/4	1/4	5/8	1-3/4	313177

End Mills

Cobalt M42 – 6 Flute – Center Cut – Weldon Shanks

Regular Length – Inch



Long Length – Inch



Cutter Diameter (Inch)	Shank Diameter (Inch)	Length of Cut (Inch)	Overall Length (Inch)	Code
1-1/16	3/4	1-1/2	3-7/8	930351
1-3/16	3/4	2	4-1/4	930356
1-1/4	1-1/4	2	4-1/2	930360
1-5/16	3/4	2	4-3/8	930361
1-3/8	1	2	4-1/2	930362
1-1/2	1-1/4	2	4-1/2	930365
1-5/8	1-1/4	2	4-1/2	930366
1-3/4	1-1/4	2	4-1/2	930367
1-7/8	1-1/4	2	4-3/8	930368
2	1-1/4	2	4-1/2	930370

Cutter Diameter (Inch)	Shank Diameter (Inch)	Length of Cut (Inch)	Overall Length (Inch)	Code
1-1/16	3/4	2	4-1/4	930411
1-1/8	1	4	6-1/2	930412
1-3/4	1-1/4	4	6-1/2	930417