


Micro-Sensitive Drill Feed Adapter



- Micro-sensitive drill adapter only - chuck and drill sold separately
- 3/4" travel
- Simple to use:
 - Grasp free-turning knurled ring and feed with gentle finger pressure
 - Spring-loaded - when ring is released, chuck retracts automatically
- Sensitive drill feeds makes drilling of small holes easy by giving you fingertip feed control independent of coarser quill feed
- Makes drilling of small holes easy by giving you fingertip feed control
- Eliminates the need for special machines to drill small holes
- Reduces breakage and deflection of small drills

Shank Diameter (Inch)	Jacobs Taper	Code
1/2	JT0	820383

Micro Drill Chuck & Key

- Very accurate and sensitive for precise drilling
- To be used in mills, lathes, drill presses, jig bore and Swiss machines
- Eliminates the need of secondary operations to drill small holes
- Spindle speeds up to 50,000 RPM
- Feed with gentle finger pressure
- Free turning knurled ring with spring return upon release
- 3/4" total travel
- Standard 1/2" diameter straight shank or MT1 to go directly into the spindle of the machine

Model	Capacity (Inch)	Jacobs Mount	Diameter (Inch)	Length Closed (Inch)	Length Open (Inch)	Code
L40I29B	1/64 - 5/32	JT0	0.866	1.102	1.378	827812

Drill Chuck Arbors

Hardened & Ground



Shank	Jacobs Taper	Code
MT1	J0	357200
MT2	J0	357210
1/2"	J0	360250
R8	J0	363330
MT1	J1	357201
MT2	J1	357211
MT3	J1	357221
1/2"	J1	360251
5/8"	J1	360261
ISA30	J1	363301
R8	J1	363331
MT1	J2	357202
MT2	J2	357212
MT3	J2	357222
MT4	J2	357232
MT5	J2	360242
1/2"	J2	360252
5/8"	J2	360262
3/4"	J2	360272
1"	J2	360282

Shank	Jacobs Taper	Code
ISA30	J2	363302
ISA40	J2	363312
ISA50	J2	363322
R8	J2	363332
MT1	J3	357203
MT2	J3	357213
MT3	J3	357223
MT4	J3	357233
MT5	J3	360243
1/2"	J3	360253
5/8"	J3	360263
3/4"	J3	360273
1"	J3	360283
ISA30	J3	363303
ISA40	J3	363313
ISA50	J3	363323
R8	J3	363333
MT1	J4	357204
MT2	J4	357214
MT3	J4	357224

Shank	Jacobs Taper	Code
MT4	J4	357234
MT5	J4	360244
1/2"	J4	360254
5/8"	J4	360264
3/4"	J4	360274
1"	J4	360284
ISA30	J4	363304
ISA40	J4	363314
ISA50	J4	363324
R8	J4	363334
MT1	J5	357205
MT2	J5	357215
MT3	J5	357225
MT4	J5	357235
MT5	J5	360245
ISA50	J5	363325
R8	J5	363335
MT1	J6	357206
MT2	J6	357216
MT3	J6	357226

Shank	Jacobs Taper	Code
MT4	J6	357236
MT5	J6	360246
1/2"	J6	360256
5/8"	J6	360266
3/4"	J6	360276
1"	J6	360286
ISA30	J6	363306
ISA40	J6	363316
ISA50	J6	363326
R8	J6	363336
MT1	J33	357207
MT2	J33	357217
MT3	J33	357227
MT4	J33	357237
1/2"	J33	360257
5/8"	J33	360267
3/4"	J33	360277
1"	J33	360287
ISA30	J33	363307
ISA40	J33	363317
ISA50	J33	363327
R8	J33	363337