

## Toggle Clamp Spindle Accessories

### Adjustable Spindle Assemblies

#### Standard Adjustable



Model	Description	Code	Model	Description	Code
SA-08034	8-32 x 3/4 (Nylon)	412210	SA-38300	3/8-16 x 3	412216
SA-10118	10-24 x 1-1/8	412211	SA-38400	3/8-16 x 4	412217
SA-14112	1/4-20 x 1-1/2	412212	SA-12300	1/2-13 x 3	412218
SA-14134	1/4-20 x 1-3/4	412213	SA-12412	1/2-13 x 4-1/2	412219
SA-56200	5/16-18 x 2	412214	SA-58500	5/8-11 x 5	412220
SA-56212	5/16-18 x 2-1/2	412215			

#### Pointed Tip Bonded Neoprene Cap



Model	Description	Code	Model	Description	Code
CC-10138	10-24 x 1-3/8	412221	CC-56212	5/16-18 x 2-1/2	412224
CC-14134	1/4-20 x 1-3/4	412222	CC-38312	3/8-16 x 3-1/2	412225
CC-14218	1/4-20 x 2-1/8	412223			

#### Model SF



Model	Description	Code	Model	Description	Code
SF-14214	1/4-20 x 2-1/4	412230	SF-38300	3/8-16 x 3	412232
SF-56234	5/16-18 x 2-3/4	412231	SF-12400	1/2-13 x 4	412233

### Flanged Washers for U-Bar Clamps Only



Model	Description	Code	Model	Description	Code
FW-080	For #8 spindle	412240	FW-516	For 5/16 spindle	412244
FW-100	For #10 spindle	412241	FW-380	For 3/8 spindle	412245
FW-140	For 1/4 spindle	412242	FW-120	For 1/2 spindle	412246
FW-141	For 1/4 spindle	412243	FW-580	For 5/8 spindle	412247

### Neoprene Caps

#### Slips on Standard Adjustable Spindle Heads



Model	Description	Code	Model	Description	Code
NC-140	For 1/4 spindle	412250	NC-380	For 3/8 spindle	412252
NC-516	For 5/16 spindle	412251	NC-120	For 1/2 spindle	412253